

A diagram of a rectangular plate with a large 'J' shape cutout. Various points are labeled with numbers and arrows: 14 points to the top-left corner; 20 points to the top-left corner of the 'J' cutout; 12 points to the vertical stem of the 'J'; 18 points to the bottom-left corner; 6 points to a point on the right edge; 8 points to a point on the right edge; 10 points to a point on the right edge; 12 points to a point on the right edge; 16 points to the bottom-right corner. A curved arrow labeled '21' points towards the right side of the plate.

A diagram of a rectangular field. A diagonal line runs from the top-left corner to the bottom-right corner. On the left side of the field, there are two points: a small dot labeled '14' and a larger dot labeled '12'. On the right side, there are four points: a small dot labeled '5', a larger dot labeled '20', a larger dot labeled '42', and a small dot labeled '44'. At the bottom-right corner, there is a small dot labeled '16'. An arrow points from the right towards the field, labeled '46'.

FIG. 1G




FIG. 2




FIG. 3

109967445-092804




FIG. 4A




FIG. 4B